

## Marylebone W1

The windows in this grade II listed family home had been well looked after over many years. However, while all the windows were in good condition they were still very draughty and let in pollution and traffic noise from a busy London street outside.

## Procedure: overhaul and draught proofing

All windows we overhauled, draught proofed and fitted with new insurance rated security locks. This made a dramatic improvement to the window insulation and gave the owners a much improved living environment without the need to change the look of the original 19th century windows.







